




EVAP Test



FLI	CANP	EVAPCV	TIME
64%	0%	100%	0s

RPM	IAC
1420RPM	63%

FTPress 1.8V



Checking bleed up rate

