


Check the Alignment of the Exhaust Camshaft Tone Ring. If Damaged or Out of Specs, Replace the Camshaft Assembly.

Helpful procedure for checking camshaft alignment on a 2.0L Contour.



Schematic for checking the Variable Camshaft Timing solenoid.