

Select Option

[DTC's w/TSB](#) or [SSMs](#) Information

P0174 - PCM

P0455 - PCM

Engine CMDTCs

P0174 - PCM

P0303 - PCM

P0455 - PCM

Freeze Frame Data

P0303 - PCM

Powertrain Control Module

Description - P0455

Evaporative Emission Control system leak detected (gross leak)

Missing or loose fuel filler cap

Suspect damaged evaporative system vapor line(s).

This [DTC](#) may be caused by :

Vacuum supply leakage / restriction

Suspect evaporative system vacuum or vapor hose leak.

[EVAP](#) canister purge valve stuck closed.

[EVAP](#) canister vent solenoid stuck open.

[EVAP](#) canister

[FTP](#) sensor

Function of the [ORVR](#) system.

OR

[EVAP](#) System Leak Detection Pump